

02910.000072



*WJC*  
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: )  
TOSHIRO TOMONO ET AL. ) : Examiner: Marvin P. Crenshaw  
Appl. No.: 10/630,805 ) : Group Art Unit: 2854  
Filed: July 31, 2003 ) : Confirmation No.: 9791  
For: IMAGE FORMING APPARATUS ) :  
U.S. Patent No.: 6,873,822 B2 ) : Certificate  
Issued: March 29, 2005 ) : JUN 23 2005  
                                  ) : of Correction  
                                  ) : June 16, 2005

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

86/17/2005 SSITHIB1 00000046 6873822  
FC:1811  
100.00 op

*JUN 23 2005*

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



---

Lawrence A. Stahl  
Attorney for Patentees  
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

LAS:eyw

JUN 23 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,873,822 B2

DATED : March 29, 2005

INVENTOR(S) : TOSHIRO TOMONO ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 55, "across sectional" should read --a cross-sectional--.

Line 58, "cross sectional" should read --cross-sectional--.

COLUMN 3:

Line 16, "cross sectional" should read --cross-sectional--.

Line 39, "cross sectional" should read --cross-sectional--.

Line 41, "cross sectional" should read --cross-sectional--.

Line 44, "manually" should read --manual--.

Line 62, "manually" should read --manual--; and "tray" should read --trays--.

COLUMN 4:

Line 8, "on" should read --onto--.

COLUMN 8:

Line 51, "of gaps" should read --of the gaps--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,873,822 B2

No. of add'l. copies  
@ 30¢ per page



Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,873,822 B2

DATED : March 29, 2005

INVENTOR(S) : TOSHIRO TOMONO ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 9, "plane," should read --plane, and--.

Line 17, "an a" should read --and a--.

Line 22, "in a" should read --in an--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,873,822 B2

No. of add'l. copies  
@ 30¢ per page

